

Update your Obsolete Analog Feedback Device with *Reliable* Digital Feedback

(without updating your entire system!)

WHAT SHOULD I UPDATE?

GE BC42 AND BC46 Models


WHY SHOULD I CONVERT?

Analog feedback devices are **expensive** to replace and to maintain, not to mention those spare parts are hard to find!
Analog technology is **outdated**...Digital technology is modern AND reliable!

WHY DYNAPAR'S SOLUTION?


Our retrofit package offers 2 options that are **RELIABLE** and **EASY** to install! Both packages include NorthStar digital tachometers that accommodate your mounting requirements.

Save **TIME**, Save **MONEY**, Save **SPACE**
with *Dynapar's Retrofit Options!*



REPLACE YOUR OLD ANALOG TACHOMETER...


... with a Dynapar digital tach **PLUS** voltage converter



OPTION #1

NorthStar RIM Tach
8500 NexGen

Eliminate your couplings



OPTION #2

NorthStar RIM Tach
6200 NexGen

Keep your couplings



RIMFV



DYNAPAR
INNOVATION • CUSTOMIZATION • DELIVERY

Contact us for more information:

E: custserv@dynapar.com

P: 1.800.873.8731