

# Update your Obsolete Analog Feedback Device with *Reliable* Digital Feedback

(without updating your entire system!)

## WHAT SHOULD I UPDATE?

GE BC42 AND BC46 Models


## WHY SHOULD I CONVERT?

Analog feedback devices are **expensive** to replace and to maintain, not to mention those spare parts are hard to find!  
Analog technology is **outdated**...Digital technology is modern AND reliable!

## WHY DYNAPAR'S SOLUTION?


Our retrofit package offers 2 options that are **RELIABLE** and **EASY** to install! Both packages include NorthStar digital tachometers that accommodate your mounting requirements.

Save **TIME**, Save **MONEY**, Save **SPACE**  
with *Dynapar's Retrofit Options!*



## REPLACE YOUR OLD ANALOG TACHOMETER...


... with a Dynapar digital tach **PLUS** voltage converter



OPTION #1

NorthStar RIM Tach  
8500 NexGen

*Eliminate your couplings*



*Keep your couplings*

OPTION #2

NorthStar RIM Tach  
6200 NexGen



RIMFV



**DYNAPAR**  
INNOVATION • CUSTOMIZATION • DELIVERY

Contact us for more information:

E: [custserv@dynapar.com](mailto:custserv@dynapar.com)

P: 1.800.873.8731